

Auto power-off	Details of operation: The power cuts off when "0" is displayed continuously for 1 minute. Operation is not performed for approx. 10 minutes. To deactivate: Power ON while pressing the POW key.
Battery Level Indicator	Details of operation: Displays 4 levels of remaining battery. *Refer to "Replacing Battery".
Back light	Activate/De-activate: Press X key for 2 seconds or longer. (About 15 seconds lighting.) Frequent use of backlight reduces battery life.
Liquid crystal display (LCD) reversal	Details of operation: Automatically reverses when the Manual Reverse key is pressed. Manual Reverse: Pressing the DISP key once. *Refer to "Opening and Closing the Display Panel".
Bar graph	Shows the proportion of the measured value to the range. *OVER, which is a high crest factor current is indicated, which means an out of the accuracy range. *Refer to "Crest factor".
Over Range Display	

Measurement Procedures

Pre-Preparation Inspection (Check the following before using the instrument.)

- Before using the instrument the first time, verify that it operates normally to ensure that no damage occurred during storage or shipping. If you find any damage, contact your dealer.
- The jaws or the case shall be free of damage. (If damage has occurred, avoid using the instrument. Use of the instrument under these conditions may result in electric shock.)
- The mating portions of the jaws should be free of any scratches or cracks.
- Battery power should be near full capacity when power is turned on. (Refer to "Replacing Battery")
- The reading should be around 0 A when no measurement is being made.

⚠ DANGER

- This instrument should only be connected to the secondary side of a breaker, so the breaker can prevent an accident if a short circuit occurs. Connections should never be made to the primary side of a breaker, because unrestricted current flow could cause a serious accident if a short circuit occurs.
- To avoid electric shock, do not touch the portion beyond the protective barrier during use.

⚠ CAUTION

- Be careful to avoid dropping the instrument, or otherwise subjecting them to mechanical shock, the jaws tip will be damaged, negatively influencing measurement.
- Do not input current greater than 1000 A. It will damage the device.

NOTE

- Please note that waveforms that include elements outside the frequency characteristic range may not be measured correctly.
- Correct measurement may be impossible in the presence of strong magnetic fields, such as near transformers and high-current conductors, or in the presence of strong electromagnetic fields such as near radio transmitters.

AC Current Measurement

⚠ DANGER


To avoid short circuits and potentially life-threatening hazards, never attach the instrument in current measurement mode to a circuit that operates at more than the maximum rated voltage CAT III 600 V, CAT IV 300 V, or over bare conductors.

NOTE

- Correct measurement may be impossible for the case of rush current or significantly fluctuating current.
 - There are cases when an error could be larger depending on positioning of sensors and conductor.
 - When the measuring value exceeds 1000 A the digital display will blink.
 - Waveforms around 20 Hz or below may be displayed as "----".
 - At a low temperature, there are cases when the reading may not be around 0 A without any input signal. But it does not affect measurement.
- Open Jaws to Power On.

1. Clamp the tester on the conductor, so that the conductor passes through the center of the clamp core.
 - Clamp the tester on one wire only.
 - Put the conductor perpendicular to the sensor, as shown in the sketch.

2. The effective value is shown on the digital display.
 - Put the conductor perpendicular to the sensor, as shown in the sketch.




Display example




Crest factor

"Crest factor = Waveform peak value/intermal rated range" is defined if or this instrument. There are cases when the accurate measurement cannot be performed with our previous models, because a top portion of the waveform is clipped off due to the rated range if a high crest factor current (RMS is low and a waveform peak is high) is input. This instrument defines the range based on the crest factor. As for a high crest factor current, its measured value becomes small to the range. If a current exceeding a crest factor of 2.8 is input, "OVER" is displayed. This measurement is the output of accurate guarantee range and the measured value is for reference purpose only.



Previous models



3291-50

Regarding the MAX value display

- (1) Press the MAX key once to confirm the MAX value. When ever a maximum value is updated, the display will be updated.
- (2) A maximum value will be cleared by pressing [MAX] key and [HOLD] key simultaneously whether when a maximum value is displayed or an instantaneous value is displayed.

NOTE

- As far as the Data Hold mode is on, MAX value cannot be updated.
- The MAX value is cleared with FILTER ON/OFF.

Filter function

The default setting of Filter is OFF. Please change the setting according to the use.

Replacing Battery

- To avoid electric shock when replacing the battery first disconnect the clamp from the object to be measured. After replacing the batteries, replace the cover and screws before using the instrument.
- Use only CR2032 lithium battery. Use of any other battery may result in explosion.
- Be sure to insert them with the correct polarity. Otherwise, poor performance or damage from battery leakage could result.
- Battery may explode if mistreated. Do not short-circuit, recharge, disassemble or dispose of in fire.
- Handle and dispose of batteries in accordance with local regulations.
- Keep batteries away from children to prevent accident and swallowing.
- To avoid corrosion from battery leakage, remove the batteries from the instrument if it is to be stored for a long time.

NOTE

- The upper left on the display screen indicates the remaining power level. When the battery approaches the exhausting power, **⚡** is displayed and a few minutes later, power turns off automatically. When **⚡** is displayed, the accuracy of measurement value is not guaranteed. Replace the new batteries soon.
- At a low or high temperature, the battery life is reduced faster.
- The batteries included with the device were installed for factory testing purposes. CR2032 lithium batteries can be purchased at electronics and appliance stores where specialized batteries are sold.
- Although the remaining power level indicator may become lower for a moment due to the internal processing, it is not an anomaly.

Replacing the Batteries

1. Loosen
2. Tighten



Position the battery so that the plus (+) side is on top.




1. Press and hold the POWER OFF key for 2 seconds or longer to turn off the device's power.
2. Remove the battery cover screws on the back of the device with a Phillips screwdriver, then remove the battery cover.
3. Replace with a new battery. When inserting a new battery (CR2032 lithium battery), be sure to position the polarities in their proper orientations.
4. Replace the battery cover and fasten the screws.

CALIFORNIA, USA ONLY
This device contains a CR Coin Lithium Battery which contains Perchlorate Material - special handling may apply.


Opening and Closing the Display Panel

Adjust the angle of the display panel for better viewing.

- Take the measurements with the display panel flipped open in order to view the measurement results more clearly, especially in tight locations, without needing to twist the jaw at an awkward angle.




The display can also be reversed by pressing the **DISP** key.



Attaching the strap

Fix the strap for fall prevention.



Make the air gap through the hole just like the figure shown.

Error Display

When an error is displayed on the LCD, the HiTester requires repair. Contact your supplier or Hoki representative.

Error Display	Meaning	Remedial Action
Err0	Internal ROM Error	Repair is necessary. Contact your supplier or Hoki representative.
Err1	Calibration Data Faulty	
Err2		
Err3		