

532K

Process Display
Temperature display for
J, K and N thermocouples

Installation and Operating Manual



Summary

1 Short description 2

2 Safety instructions and warnings 2

2.1 Use according to the intended purpose 2

3 Mounting.....3

3.1 Installation 3

3.2 Electrical connection 3

4 Start-up.....3

5 Programming.....3

5.1 Switching to programming 3

5.2 Changing the parameter setting 4

5.3 Saving the parameter setting 4

5.4 Programming 4

5.5 End of programming 5

6 Operation.....7

6.1 Switching the display during operation 7

6.2 Saving the momentary value 7

7 Error and alarm messages 7

8 General technical features 8

8.1 Electrical features 8

8.2 Mechanical features 8

8.3 Environmental conditions 9


9 Scope of delivery.....9

10 Order code.....9

11 Dimensions.....10

- Subject to change without prior notice -

Note :
The fields with a grey background contain the
factory-set default values.



1 Short description

This digital display is an easy-to-use, microprocessor-controlled device for the display (and the acquisition) of measured temperature values. The temperatures are measured by means of J, K and N thermoelectric couple sensors. They can display either the current measured value, the maximum value or the minimum value. In case of power switch-off, the maximum and minimum values are stored in an EEPROM. The values are restored as soon as the display is powered again. The Latch input is isolated electrically from the signal input by means of an optocoupler. It allows storing the current measured value.

The supply voltage (10 .. 30 V DC) is isolated electrically from the signal input by means of a DC/DC converter.



2 Safety instructions and warnings



Only use this display
– **in a way according to its intended purpose**
– **if its technical condition is perfect**
– **adhering to the operating instructions and the general safety instructions.**

1. Before carrying out any installation or maintenance work, make sure that the power supply of the digital display is switched off.
2. Only use this digital display in a way according to its intended purpose.
3. If its technical condition is perfect.
4. Adhering to the operating instructions and the general safety instructions.
5. Adhere to country or user specific regulations.
6. The digital display is not intended for use in areas with risks of explosion and in the branches excluded by the standard EN 61010 Part 1.
7. The digital display shall only operate if it has been correctly mounted in a panel, in accordance with the chapter "Main technical features".

2.1 Use according to the intended purpose

The digital display only may be used as a panel-mounted device. Applications of this product may be found in industrial processes and controls, in the branch of the manufacturing lines for the metal, wood, plastics, paper, glass, textile, etc., processing industries. Overvoltages at the terminals of the digital display must be limited to the values of overvoltage category II.

If the digital display is used to monitor machines or processes in which, in case of a failure of the device or an error made by the operator, there might be risks of damaging the machine or causing accidents to the operators, it is up to you to take appropriate safety measures.

3 Mounting

3.1 Installation


1. The digital display shall not be installed near to contactors or motor starters.
2. We recommend the use of wire end ferrules in order to avoid short-circuits between adjacent terminals.
3. In order to keep the interferences at the measuring input as low as possible, the signal and power supply wires must be routed separately.
4. Use shielded cables for all signal/probe wirings and avoid routing the signal/probe wirings parallel to each other. The shield shall only be grounded at one point in order to avoid ground loops.

Important note:


Before carrying out any installation or maintenance work, make sure that the power supply of the digital display is switched off.

3.2 Electrical connection

3.2.1 Thermoelectric couple sensor




3.2.2 Supply voltage and Latch input connection




4. Start-up

After switching on the supply voltage:


1. a display test is carried out (Duration: 2 seconds)




3. the selected probe is displayed (Duration: 2 seconds).



2. Device type and software version are displayed (Duration: 2 seconds)



4. the display is ready to operate and the measured value is displayed.




5. Programming


5.1 Switching to programming

To switch to the programming mode:


1. switch the power supply of the device off, press simultaneously both keys on the front side, and then switch the power supply on again.



2. The display shows the following message.



3. release both keys. The first parameter to be set appears on the display. The display switches every second between the following messages



4. press the left key to stop the display from switching. The last programmed parameter setting is displayed.

5.2 Changing the parameter setting

1. press the right-hand/grey key to change the parameter setting by one value at a time



2. to input numerical values, select first the decade with the left-hand/red key




3. the decade blinks

4. set now the numerical value using the right-hand/grey key




5. to reach the following decade, press the left-hand/red key



6. if negative numerical values are required, set the left decade to “-” or “-1”.

5.3 Saving the parameter setting and switching to the following parameter

1. keep the left/red key pressed




2. and press simultaneously the right/grey key.




5.4 Programmng the adjustable parameters

5.4.1 Input signal type



Range


Selection in the menu



Thermoelectric couple J




Thermoelectric couple K



Thermoelectric couple N

Note :

The fields with a grey background contain the **factory-set** default values.



5.4.2 Reference point compensation

A thermoelectric temperature measurement measures a (thermoelectric) voltage generated by a thermoelectric couple. The value of the thermoelectric voltage depends on the temperature difference between the measured point and the reference point.


In order to define accurately the temperature at the measured point, the temperature of the reference point must be constant and/or known. To do so, the internal and external reference points are differentiated.

For the internal reference point compensation, the device is fitted with an internal temperature sensor that measures the current temperature of the terminal. This

temperature is used to compensate the measured thermoelectric voltage. This measuring method requires to connect the sensor with the terminal of the display by means of appropriate compensation lines. These terminals are the internal compensation point.


When using the external reference point compensation, the temperature of the reference point is maintained at a constant and known value by means of appropriate measures. The temperature sensor is connected with the device, which is set to the constant temperature of the reference point, by means of a simple copper wire.

5.4.2 Reference point compensation (Continued)


 Reference point compensation

Selection in the menu


 Internal reference point compensation

 External reference point compensation
Adhere to point 5.4.2.1

5.4.2.1 External reference point temperature

 External reference point temperature

Selection in the menu



Input of the known value of the external reference point temperature in 0,1 °C/0,1 °F, according to the temperature unit set

5.4.3 Decimal point


 Decimal point

Selection in the menu


 Resolution 0,1 °C/0,1 °F


 Resolution 1 °C/1 °F

5.4.4 Temperature unit

 Unit

Selection in the menu


 Display in °C

 Display in °F

5.4.5 Correction value

Inputting a correction value allows acting upon the displayed result. These correction values may be

positive or negative. The input is always made with one decimal place.

 Setting the correction value


Selection in the menu




Correction value in 0,1 °C/0,1 °F, depending on the unit selected

5.4.6 Maximum value acquisition


The maximum value may be saved and consulted during operation (see 6.1)



Selection in the menu




Maximum value acquisition on




Maximum value acquisition off

5.4.6.1 Resetting the maximum value


This allows defining whether the maximum value can be reset during operation or not. However, the maximum value can only be reset if the maximum value display is the active function (see 6.1). If the maximum value is reset, the current measured value becomes the new maximum value.



Selection in the menu




The maximum value can be reset using the red key




The maximum value cannot be reset

5.4.7 Minimum value acquisition


The minimum value may be saved and consulted during operation (see 6.1)



Selection in the menu




Minimum value acquisition on




Minimum value acquisition off

5.4.7.1 Resetting the minimum value


This allows defining whether the minimum value can be reset during operation or not. However, the minimum value can only be reset if the minimum value display is the active function (see 6.1). If the minimum value is reset, the current measured value becomes the new minimum value.



Selection in the menu




The minimum value can be reset using the red key



The minimum value cannot be reset

5.5 End of programming


When programming is finished, end the programming routine as follows:



Selection in the menu



Programming restarts. The set values can be checked and modified.



Programming is finished. The set values are used in operation.

6. Operation

6.1 Switching the display during operation


press the right-hand/grey key to select among the following functions:

- current measured value
- minimum value
- maximum value.


Press the key once to display the designation of the active display function for 2 seconds. If, **during this time**, the right-hand grey key is **pressed a second**

time, the display switches to the following display function. This is confirmed by a 2-second display of the designation of the new function. After these 2 seconds, the display shows, depending on the selection, the maximum value, the minimum value or the current measured value.


1. Current measured value, press once the right-hand/grey key




3. Maximum value (when active), press once the right-hand/grey key



2. Minimum value (when active), press once the right-hand/grey key



4. Current measured value, press once the right-hand/grey key



6.2 Saving the momentary value (Display-Latch)

In case of a High Signal at the Latch input, the current measured value is frozen on the display. The minimum

and maximum value acquisition continues operating in the background.

7 Troubleshooting and alarm messages


7.1 Display does not light up

If the **display does not light up**, check the supply voltage or the power supply cables. Do not open the housing by force.

7.3 Input problems



7.2 Measuring rang overflow or underflow



8 Main technical features

Operation:

by means of two front panel keys

Display:

5-digit display, red 7-segment LED's,
Height of the figures 8 mm

Display range:

(see temperature range), with leading zeros
suppression Measuring range overflow, indicated by ooooo on the display.
Measuring range underflow, indicated by uuuuu on the display.

8.1 Electrical features

Input:

Thermoelement-sensor
J (Fe-CuNi)
K (Ni-CrNi)
N (NiCrSi-NiSi)

Temperature ranges:

after DIN IEC 548
J (Fe-CuNi) -210,0 °C ... +1200,0 °C
-346,0 °F ... +2192,0 °F
K (Ni-CrNi) -200,0 °C ... +1372,0 °C
-328,0 °F ... +2501,6 °F
N (NiCrSi-NiSi) -200,0 °C ... +1372,0 °C
-328,0 °F ... +2372,0 °F

Resolution:

0,1°C (0,1°F) or 1°C (1°F)

Reference point compensation:

internal or external (programmable)

Reference point error:

+/-1,0 °C typ.
+/-3,0 °C max.

Linearity error:

< 0,4 % for the whole measuring range at an
ambient temperature of 20°C

Temperature drift:

0,1 K/K_{ambient}

Measuring rate:

5 measurements/second, fixed

Display refresh:

1 ... 2 times per second

Display Latch input:

Display stop for the current measured value,
active for log. 1
Switching log. 0: 0 ... 2 VDC
level log. 1: 4 ... 30 VDC

Supply voltage:

10 ... 30 V DC, electrically separated,
with Verpolschutz

Current consumption:

max. 40 mA

Test voltage:

500 V_{eff}; 50/60 Hz; 1 min

Data backup:

EEPROM

8.2 Mechanical features

Housing:

Housing for control panel 48 x 24 mm
according to DIN 43 700, RAL 7021

Dimensions (W x H x D):

48 x 24 x 66 mm

Panel cut-out (W x H):

45^{+0,6} x 22,2^{+0,3} mm

Mounting depth:

approximately 59 mm

Weight:

approximately 50 g

Protection level:

IP 65 (on the front side)

Connection:

Screw terminal, RM 5.08, 7 poles

Connection diameter:

single-wire 0,14 .. 1,5 mm²
thin wire 0,14 .. 1,5 mm²
wire dimensions AWG 26-16

8.3 Environment conditions

EMC:

according to EC EMC directive 89/336/EEC
Interference emissions EN 50081-2 /
EN 55011 Class B
Interference resistance EN 61000-6-2

Operating temperature:

-20 °C ... +65 °C, relative humidity < 85%

Storage temperature:

-25 °C ... +70 °C


9 Scope of delivery

Digital display
Clamp
Front panel for clamp mounting,
Panel cut-out 50 x 25 mm
Front panel for screw mounting,
Panel cut-out 50 x 25 mm
Seal
Multilingual operating instructions
1 set of self-adhesive symbols


10 Order code

532K

11 Digital display dimensions



Panel cut-out



Mounting frame

