



HPC50 Series Operation Manual

for the HPC50 Series Intrinsically Safe Handheld Pressure Calibrator



AMETEK
SENSORS, TEST & CALIBRATION

Contents

Overview	1	Enclosure	20
Introduction	1	APMi Modules	21
Quickstart	2	ATMi Modules	22
Functions	3	Specifications	23
On/Off	3	Ranges and Resolutions	28
Navigation	3	Safety & Certifications	29
Settings	6	Hazardous Locations	29
Display	8	Certifications	29
Operation	9	Multi-language Safety Instructions	30
Pressure Sensors	9	Support	31
Measuring Current	13	Troubleshooting	31
Sourcing Current	14	Calibration	32
Measuring Voltage	15	Accessories and Replacement Parts	33
Measuring Temperature (ATMi)	16	Contact Us	34
Performing a Switch Test	17	Warranty	34
Calibrating a Pressure Transmitter	18		

Overview

INTRODUCTION

Thank you for choosing the HPC50 Series intrinsically safe handheld pressure calibrator from Crystal Engineering Corporation. HPC50 calibrators feature dead-weight tester accuracy in a modern digital package with the safest fitting connection available. The full color display features an easy to use interface and may be used in a broad range of applications from simple tool type jobs to complex calibration jobs in custody transfer systems.

Accuracy is up to 0.035 percent of reading—so one HPC50 can typically replace several gauges or calibrators you may have been using. The HPC50 is fully temperature compensated—so there is no change in accuracy throughout the entire operating temperature range!

Single and dual pressure sensor models are available from vacuum up to 10 000 psi / 700 bar. In addition, the HPC50 features the ability to add up to two external pressure ports (APMi) to provide up to four pressure ports. When included with a barometric reference (BARO option), all pressure readings can be displayed as gauge or absolute readings.

In addition to pressure measurement, the HPC50 also includes inputs for mA, voltage, switch testing, and up to two temperature measurement modules (ATMi).

HPC50 Series Measurement Options

Measurement Type	Available Modes (as defined on display)
Pressure	P1, P2, APMi1, APMi2, Diff. Pres, Dual Pres.
Temperature	ATMi1, ATMi2
Barometric Pressure	BARO
Current	mA In
Voltage	VDC In
Switch Test	Switch Test

Other features include:

- User configurable information display
- % error calculation
- % flow calculation
- Scaling
- Damping
- Leak Testing
- Min/Max hold
- Uses Crystal's patented CPF fittings and hose system (leak-free and finger-tight to 10 000 psi (700 bar))

QUICKSTART

APMi and ATMi Module Connections

Connect 1 or 2 external modules to expand measurement options. The APMi module for pressure, and the ATMi module for temperature.

"Wireless" Keypad

All input and output connectors are placed away from the display and keypad to give maximum freedom to operate.

Mini-USB Port

Customize the set-up through free CrystalControl software.

Function Buttons

The function of each button is clearly explained on the bottom of the display.

Protective Boot

Required for Intrinsic Safety.



Color Display

The large, full-color, sunproof display combined with the advanced simplicity of the user interface, makes the HPC50 Series the easiest-to-use pressure calibrator available.

Cursor Keys

Cursor keys help you to navigate through the display to perform set up functions and fine tune values.

CPF Pressure Connections

Includes patented, leak-free, finger-tight CPF connection fittings.

Unique "Non-Menu" User Interface

Easy to use single layer user interface. No deep menu structure! Operate and set up the HPC50 Series to perform your tasks quickly and intuitively.



Functions

ON/OFF

Power button



Press and hold the (power) button to turn the HPC50 Series on or off.
The HPC50 will automatically power down if not used for the time period defined in the unit settings or in CrystalControl.

Automatic Shutoff - Low Power Mode

CRYSTALCONTROL To optimize battery life, adjust your **Automatic Shutoff** time (shut off time in absence of key press) on the unit or through the free CrystalControl software. This feature is adjustable from 5 minutes to "always on."

NAVIGATION

Arrow Buttons



The (arrow) buttons serve different functions depending on the mode of operation. Press any of the four (arrow) buttons to enter "Navigation Mode". In this mode, the user can scroll through editable fields directly onscreen.

Navigation Mode: Use the four (arrow) buttons to move the cursor in the desired direction.

Edit Mode: Use the Up and Down (arrow) buttons to scroll through lists of options. Or, if entering a number, use the left and right (arrow) buttons to move the cursor one character in the desired direction.

Back Button



Press the (back) button to cancel a selection or to return to a previous menu.

Enter Button



Press the (enter) button to view/accept selected options or entered values. When a value is entered with the (enter) button, the cursor selects the next value field in the list.

Zero Button



Press the (zero) button to activate the function key options. The HPC50 will display the parameters that are currently shown on the upper and lower displays. Press the (function) button for the parameter that you would like to zero. The display will then briefly flash all dashed lines (----), indicating that it has been zeroed.

Note: If you attempt to zero the gauge with more pressure applied than the Zero Limit set on the HPC50 (or with CrystalControl) the command will be ignored, and *Over Zero Limit* will display.

Note: The BARO sensor cannot be zeroed.

! WARNING: This calibrator can display zero pressure when connected to a source of pressure! Do not rely on the display indication before disconnecting—it may not be indicating true pressure. Never disconnect pressure instrumentation without first relieving system pressure!

► To Clear the Zero Value

- 1 Press the (zero) button to activate the (function) buttons for the available pressure sensors.
- 2 Press and hold the (function) button for the sensor that you would like to unzero until the display changes from (----) to (- - -).


► To Clear the Peaks

- 1 Press the (zero) button to activate the (function) buttons for the available pressure sensors.
- 2 Press the (function) button for *Peaks* to reset the P1, P2, and APMi peaks.

Navigating Through a Typical Setup


- 1 Press any of the (arrow) buttons to enter Navigation Mode.
- 2 Use the (arrow) buttons to move between the configurable fields within the upper and lower displays.

Note: Configurable fields are *not* highlighted in light blue on the actual display; but selected fields *are* highlighted in **dark blue**.



- 3 Use the (enter) button to select a field for editing.

4 Use the up and down (arrow) buttons to select a new value, then press the (enter) button to choose the new value.



Note: To exit Navigation mode without making a selection, press the (back) button.

Calibration Due Reminder

The HPC50 Series has a calibration reminder feature that can help to assure that you never use the calibrator after its calibration certificate has expired. Set calibration due dates and warning period through our free CrystalControl software.

► Calibration Reminder Alert

Enter the Cal Due date and the warning period prior. Once the defined time prior is reached, the HPC50 will flash *Cal Soon* during the startup process. It will do this on every start-up until the calibration due date is reached, or the dates are updated.

► Calibration Due Alert

Once the calibration due date has been reached, the HPC50 will flash Cal Due during start-up. While in use, the HPC50 display will alternate displaying Cal Due and live pressure readings. This behavior will continue until the calibration date is updated through CrystalControl.

SETTINGS

Settings Button



Press the (settings) button to enter the system settings menu.

► Recall

Used to recall a saved setup.

► Save

Used to store the current display setup. Saving a setup allows for quick loading of the same configurations for later use. This makes it easy to switch between different applications or tasks. Up to 5 setups can be stored.

► General

Used to view or edit the following system settings:

- Auto Off Time
- HART resistor On/Off
- Serial Number
- Firmware Version
- Part Number

► P1, P2, and APMi

- Mode: Switch between absolute and gauge pressure
- Filter Time
- Zero Limit
- Maximum Resolution: When a resolution less than standard is selected, the displayed number will include an asterisk (*)
- Overpressure Count: Counts the times when pressure has exceeded 110% of the range
- View Calibration Details
- Serial Number
- Part Number

► **BARO**

- Maximum Resolution: When a resolution less than standard is selected, the displayed number will include an asterisk (*)
- View Calibration Details
- Serial Number
- Part Number

► **ATMi**

- Maximum Resolution: When a resolution less than standard is selected, the displayed number will include an asterisk (*)
- Probe Coefficients: Enter and modify RTD coefficients
- View Calibration Details
- Serial Number

► **mA In, mA Out (sink) and VDC In**


- Maximum Resolution: When a resolution less than standard is selected, the displayed number will include an asterisk (*)
- View Calibration Details
- Serial Number

► **To Save a Setup**

After you have configured the unit, you can save the setup for future use.

- 1 Press the (settings) button to enter the settings section.
- 2 Press the (arrow) buttons to highlight the Save Setting, and then press the (enter) button.
- 3 Press the (arrow) buttons to highlight the setup you want to modify, and then press the (enter) button.
- 4 Use the (arrow) buttons to change the name of the saved setup. When finished press the (enter) button.

The name is limited to eight characters.



Highlight the settings to modify...




then change the name of the saved setup.


- 5 Press the (F3) function button for Save.

- To Recall a Setup
- 1 Press the (settings) button to enter the settings section.
 - 2 Press the (arrow) buttons to highlight the Recall Setting, and then press the (enter) button.
 - 3 Press the (arrow) buttons to highlight the setup you want to use, and then press the (enter) button.

The name of the setup will appear in the upper-left corner



Highlight the setup...



then press enter.

DISPLAY

The display is divided into two sections: the upper and lower displays. The upper display can be configured to show values for Current, Voltage, Temperature, Pressure, BARO, or Switch Test. The lower display can be configured to show values for only Temperature, Pressure, and BARO.



Upper Display (showing Current)

Lower Display (showing Pressure)

Operation

PRESSURE SENSORS

The HPC50 Series is equipped with one or two pressure sensors. In addition, one or two intrinsically safe APMi (Advanced Pressure Module) or ATMi (Advanced Temperature Module) external modules may also be used. For information on the Crystal external modules, please refer to [APMi Modules](#) and [ATMi Modules](#). Be sure to choose the proper sensor based on working pressures and accuracy.

! WARNINGS: The following warnings apply to any sensor used with the HPC50 — whether internal or external:

- Pressure sensors may be damaged and/or personal injury may occur due to improper application of pressure. Please refer to the [Ranges and Resolutions table](#) for information on overpressure ratings.
- The calibrator will display **+OL** when an inappropriate pressure is applied. If **+OL** is displayed, the pressure should be reduced or vented immediately to prevent damage or possible personal injury.

Note: **+OL** is displayed when the pressure exceeds 110% of the nominal range of the sensor.

Pressure Connection

Crystal CPF System: Medium Pressure Female (MPF) (1/4" medium pressure tube system with 7/16-20 threads). See our [CPF brochure](#) for further information.

CPF o-ring size and material: AS568A-012, Viton 80 durometer (P/N 3981).

For most applications CPF Fittings can be hand tightened (no tools required). Wrench tightening is recommended (to achieve a metal to metal cone seal) for applications where chemical compatibility of the process fluid and the o-ring are a concern. Cone seals require only moderate assembly torque to seal up to 10 000 PSI (700 bar). We recommend a tightening torque of 120 in-lbs $\pm$ 20 in-lbs for our CPF fittings. Please note this is only a fraction of the typical torque required to seal a 1/4" NPT fitting. If a torque wrench isn't practical to use, the fittings can be assembled as follows: Hand tighten fitting fully until the cone has bottomed out, then tighten an additional 20° using a hex wrench. Apply a small amount of media-compatible lubricant to the gland threads and male cone to increase fitting life, reduce the likelihood of galling, and promote sealing.

! CAUTION:

! CAUTION: The HPC50 is not recommended for continuous use at high vacuum.

Overpressure Conditions

The HPC50 Series will read pressure up to approximately 110% of the rated pressure range. Above 110%, the display will indicate **+OL**, and readings will stop updating. The zero function does not affect when the display will indicate **+OL**, so depending on the zero value it is possible that the display will indicate **+OL** without the maximum pressure being displayed.

For instance, if a 100 psi range is zeroed when 30 psi is being applied, it will indicate that the overpressure condition has been reached at 80 psi (i.e., 110% x 100 psi – 30 psi = 80 psi).

Overpressure can affect accuracy, but the effect is only temporary unless the sensor has been destroyed. See the [Ranges and Resolutions table](#) for maximum allowable overpressure ratings.

Measuring Pressure

► To Measure Pressure

- 1 Connect the HPC50 using an appropriate fitting.
- 2 Select one of the pressure modes: **P1**, **P2**, **APMi1**, **APMi2**, **BARO**, or **Dual Pres.**
For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).
- 3 From the HPC50 display, select the desired pressure units.



Select a pressure mode... then select a pressure unit.


► Absolute Pressure (BARO Option)

See [P1, P2, APMi1 or APMi2 settings](#) to toggle between absolute and gauge pressure.

► To Zero the Calibrator

- 1 Press the (zero) button to activate the (function) buttons for the available pressure sensors.
- 2 Press the (function) button for the sensor that you would like to zero.

The display will change to dashed lines (----) and the reading will be zeroed.



Zeroing the P2 sensor.

► To Clear the Zero Value

- 1 Press the (zero) button to activate the (function) buttons for the available pressure sensors.
- 2 Press and hold the (function) button for the sensor that you would like to unzero until the display changes from (----) to (- - -).

► To Clear the Peaks

- 1 Press the (zero) button to activate the (function) buttons for the available pressure sensors.
- 2 Press the (function) button for **Peaks** to reset the P1, P2, and APM peaks.
- 3 Press the (function) button for the peaks you would like to clear. The **Hi**, **Lo**, and **Filter** will all display (- - -).

Note: If you attempt to zero the gauge with more pressure applied than the Zero Limit set on the HPC50 (or with CrystalControl) the command will be ignored, and **Over Zero Limit** will display.

Note: The BARO sensor cannot be zeroed.

! WARNING: This calibrator can display zero pressure when connected to a source of pressure! Do not rely on the display indication before disconnecting—it may not be indicating true pressure. Never disconnect pressure instrumentation without first relieving system pressure!

Differential Pressure

The HPC50 Series can display differential pressure when 2 or more sensors are installed (including external APMi). The modules do not have to be the same full scale pressure range.

► To Display Differential Pressure

- 1 Select **Diff. Pres.** from the Mode section.
- 2 Choose the two sensors that you want to use for differential pressure.
- 3 Choose the unit for the differential reading.

For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).

- 4 Apply pressure to one or both sensors to read the differential.



The two pressure sensors being used can be changed from P1, P2, or APMi.

Differential Pressure Unit

Static Pressure Unit

Note: The static pressure is also displayed on the bottom of the window. The unit for the static pressure does not have to be the same as the differential unit.

Tare

Using the Tare function improves your [differential measurement uncertainty](#) significantly if used properly. The Tare function equalizes (normalizes) the HPC50's two modules at a non-ambient datum.

If you apply the same static line pressure to both sensors simultaneously, you should have a differential reading of zero. Due to the allowable error tolerance for each module, the reading may not be zero. The Tare function allows you to normalize both readings so that the differential reading is zero. This gives you a more accurate differential reading than if this process were not completed.

Note: Tare should be reestablished every time your measurement conditions change, including vent condition. For instance if your ΔP reading has 8 inH2O of Tare at 1500 psi static, when you return to vent condition this 8 inH2O of Tare will remain in place on your ΔP reading until cleared with the Tare button.

To Tare:

- 1 Use the (arrow) buttons to navigate to the Differential Mode view.
- 2 Press the (zero) button to activate the function button options.
- 3 Press the (function) button for the (Diff) icon.

Note: You will notice that the word **Tare** is now included on the top right of the display to indicate that the sensors have been tared.

- 4 To clear the Tare value in the Differential Mode, hold the (function) button for the (Diff) icon for four seconds until the differential display readings change from (- - - -) to (- - -). The tare indication will now be removed from the display.

MEASURING CURRENT

The HPC50 is capable of measuring current in four different modes:

- **mA** Measured current is displayed (mA). The module is capable of measuring inputs up to 55 mA.
- **0-20 mA** Current is displayed as a percentage of the 0-20 mA current range of the module. Where: 0 mA = 0%, and 20 mA = 100%
- **4-20 mA** Current is displayed as a percentage of the 4-20 mA current range of the module. Where: 4 mA = 0%, and 20 mA = 100%
- **10-50 mA** Current is displayed as a percentage of the 10-50 mA current range of the module. Where: 10 mA = 0%, and 50 mA = 100%


► To Measure Current

- 1 Select **mA In**.

For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).

- 2 In current mode, the numerical value displayed represents the current measured at the test lead inputs. In the top right corner is a percentage value based on whether **0 to 20 mA**, **4 to 20 mA**, or **10 to 50 mA** is selected.

For example, if the measured current is 16 mA and the selected scale is 4 to 20 mA, the percent will display as 75%.



Measuring Current.

- 3 Connect the HPC50 using the appropriate test leads.
- 4 The HPC50 will display the measured current.

Note: The display will indicate **+OL** if the measured current exceeds the nominal range of current measurement (55 mA).

Note: For details on % error, % flow, and scaling features see [Percent Error Function](#).

SOURCING CURRENT

► mA Sink (External Loop Power Supply)

- 1 Select **mA Out**.
- 2 Select the appropriate range (0-20 or 4-20) if you will be sourcing based on the % of the scale.
- 3 Choose either **mA** (to output a specific mA signal), **%** (to output based on the % of the mA range), or **% flow** (to output based on the % of the flow).
- 4 Connect the HPC50 using the appropriate test lead connections.
- 5 Enter the desired current in mA, %, or % flow to sink.

► mA Step

The HPC50 has the ability to automatically or manually step through the mA range at predefined intervals.

- 1 Select **mA Out**.
- 2 Select the appropriate mA range (0-20, 4-20).
- 3 Press the (function) button for **Step**.
- 4 Enter the 0 and 100% mA points. For example, if you're sourcing to a 4-20 mA loop, enter 4 for the 0% point and 20 for the 100% point.
- 5 Choose the step size from 10%, 20%, or 25%. This is the percent of the mA range that will be increased with each step.
- 6 Enter the time between each step you would like to use.




- 7 Press the (function) button for **Auto**, and the HPC50 will automatically start the step process.
- 8 Press the (function) button for **back** when finished. Or, if you would like to pause the step function and increase manually, press **Stop**. If you press **Stop**, new function keys **-Step** (decreasing a single step) and **+Step** (increasing a single step) are now available.

► mA Ramp

The HPC50 has the ability to provide a consistent ramp throughout the full mA range.

- 1 Select **mA Out**.
- 2 Select the appropriate mA range (0-20, 4-20).
- 3 Press the (function) button for **Ramp**.
- 4 Enter the 0 and 100% mA points.
- 5 Enter the total time to get from 0 to 100% of the scale.



- 6 Press the (function) button for **Start** and the HPC50 will begin the ramp process.
- 7 Press the (function) button for **Stop** to pause the ramp, or **Back** to go back to the ramp setup screen.

MEASURING VOLTAGE

The HPC50 may be used to measure voltages up to 28 VDC. Voltage measurements are limited to the upper display.

► To Measure Voltage

- 1 Select **VDC In**.



For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).

- 2 Connect the HPC50 using the appropriate test leads.
- 3 The HPC50 will indicate the measured voltage.

Note: The display will indicate **+OL** if the measured voltage exceeds 30 VDC.

MEASURING TEMPERATURE (ATMi)

Your HPC50 has the ability to measure temperature very accurately using the ATMi “true ohm” technology. True ohm resistance measurement eliminates temperature reading errors by compensating for thermoelectric effects associated with the wires and connections between the ATMi and the RTD.

The HPC50 will also indicate electrical resistance (Ω) to help in troubleshooting your resistance based sensing element.


For details on the ATMi external module, see the [ATMi manual](#).

ATMi External Temperature Modules

CAUTION: ATMi modules must only be used with intrinsically safe probes provided by Ametek.

► To Measure Temperature

- 1 Connect an ATMi with RTD probe to the HPC50 Chassis in either ATMi port.



Connect an ATMi module to either port 1 or 2

- 2 Select **ATMi1** or **ATMi2**.

For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).

- 3 Select the appropriate unit from the list.

- 4 The HPC50 will display the measured temperature.

Note: **+OL** will be displayed if a probe is not connected to the ATMi, or if the probe resistance is greater than 400 Ohms and/or the calculated temperature is outside the range defined for the probe. Temperature range depends on the probe type.

PERFORMING A SWITCH TEST

Performing a switch test will require the use of both screens. The HPC50 records switch state, and pressure or temperature measurement at the time of switch change. After the test, the result is displayed in a convenient and easy-to-use format.

To Perform a Switch Test

- 1 Select **Switch Test** in the upper display.
- 2 FOR A PRESSURE SWITCH, select **P1, P2, Diff. Press., APMi1, or APMi2** in the lower display.
FOR A TEMPERATURE SWITCH, select **ATMi1 or ATMi2** in the lower display.
For more information on working in the HPC50 display, see [Navigating Through a Typical Setup](#).
- 3 Connect the HPC50 to the switch using the terminals on the top of the HPC50. (The polarity of the terminals does not matter.)
- 4 FOR A PRESSURE SWITCH, connect a pump to the HPC50 and then to the switch.
FOR A TEMPERATURE SWITCH, connect an RTD to the ATMi and place the RTD and temperature switch sensor into a temperature calibrator.
- 5 FOR A PRESSURE SWITCH Check that the vent on the pump is open, and zero the calibrator if necessary. Then close the pump vent.
The upper display will show no read outs for the **Closed**, **Opened**, and **Dead band** values.

Memory 4				
Switch Test		Reset		
Closed	----			PSI
Opened	----			
Dead band	----			

- 6 Slowly apply pressure or temperature until the switch changes state.
Once the switch state changes, the switch icon will change, and the display will indicate the pressure or temperature, at which the state changed.
Note: In the switch test mode, the sample rate is increased to ten readings per second to help capture the changing switch state. Even with this enhanced sample rate, changes to the pressure or temperature should be done slowly to ensure accurate readings.
- 7 Decrease pressure or temperature until the switch state changes.
Once the switch state changes, the icon will change, and the **Closed**, **Opened**, and **Dead band** values will be indicated.

Memory 4				
Switch Test		Reset		
Closed	----			PSI
Opened	229.68			
Dead band	----			
P2 Max.	300.00			-30.9/min

Switch Open

Memory 4				
Switch Test		Reset		
Closed	133.37			PSI
Opened	229.68			
Dead band	96.31			
P2 Max.	300.00			-26.3/min

Switch Closed

- 8 To perform a new test, highlight the reset option and press the (enter) button.
The **Closed**, **Opened**, and **Dead band** values will all be blank again.

CALIBRATING A PRESSURE TRANSMITTER

When calibrating a transmitter, both the upper and lower displays are used. Pressure and Temperature Transmitters with ranges of 0 to 20 mA, 4 to 20 mA, and 10 to 50 mA can be calibrated by an HPC50. The example below will use a 4 to 20 mA pressure transmitter.

► To Calibrate a Pressure Transmitter

- 1 Select **mA In** in the upper display and **P1** in the lower display.
- 2 Select **4 to 20mA** from the Range list.
- 3 Connect the HPC50 to the transmitter.

► HART Resistor

The HPC50 has an internal 250 Ohm HART resistor that can be selected if desired. With the (settings) button, choose **General** to select HART resistor On or Off.

► Percent Error Function

The HPC50 can be programmed to calculate a deviation or % error from 4-20 mA output. This eliminates the need for manual calculations and can also be helpful if it becomes difficult to set an exact pressure with an external pump. The HPC50 simultaneously displays pressure, mA, and percent error.

- 1 Select **% Error** from the mA units selection in the upper window.
- 2 Use the (arrow) buttons to set the 0 and 100% points for both the mA and pressure ranges of the transmitter.




- 3 Increase pressure to the desired point and the HPC50 upper display will indicate the % error as well as the actual mA value. The lower display will show the measured pressure.

► **Percent Flow Function**

The HPC50 can calculate the flow percentage for a differential pressure transmitter. The square root of the differential pressure across an orifice plate is proportional to the flow. The differential pressure is simulated or measured via the mA current and the resultant calculations are then scaled from 0 to 100%.

- 1 Select **% Flow** from the mA units selection in the upper window.
- 2 Use the (arrow) buttons to set the 0 and 100% points for both the mA and pressure ranges of the transmitter.



- 3 Increase pressure to the desired point and the HPC50 upper display will indicate the % error as well as the actual mA value. The lower display will show the measured pressure.

	4-20 Flow	0-20 Flow
0%	4	0
25%	5	1.25
50%	8	5
75%	13	11.25
100%	20	20

► **Scaling Function**


The HPC50 has the ability to read current or voltage in the upper display that is scaled to and displayed in the same units as the lower display. This makes it much easier to compare a mA reading to a known accurate pressure reading.

- 1 Select **Scaling** from the mA units selection in the upper window.
- 2 Use the (arrow) buttons to set the 0 and 100% points for both the mA (or VDC) and pressure ranges of the transmitter.
- 3 Increase pressure to the desired point and the HPC50 upper display will indicate the equivalent pressure based on the mA reading, as well as the actual mA value. The lower display will show the measured pressure.

Enclosure

INFORMATION

Weight 567 g (20.0 oz) (Weight is for dual sensor model with protective boot installed, and includes batteries).
Housing PC/PBT Plastic.
Rating IP66/67.
Keypad and Labels UV Resistant Silicone.



APMi Modules

ACCURACY

psi (Gauge Pressure)

► 18 to 28° C

0 to 30% of Range:±(0.01% of Full Scale)
 30 to 110% of Range:±(0.035% of Reading)
 Vacuum*:±(0.05% of Full Scale**)

► -20 to 50° C

0 to 30% of Range:±(0.015% of Full Scale)
 30 to 110% of Range:±(0.050% of Reading)
 Vacuum*:±(0.05% of Full Scale**)

* Applies to 300 psi / 30 bar / 3 MPa and lower ranges only.
 Vacuum Range = -14.5 psi / -1.0 bar / -1MPa.

** Full Scale is the numerical value of the positive pressure range.

psiA (Absolute Pressure with BARO Option)

All absolute accuracies are equivalent to the gauge pressure accuracies, except as noted below.

15 psi / 1 bar / 100 kPa Range: Gauge Accuracy +0.005 psiA
 30 psi / 3 bar / 300 kPa Range: Gauge Accuracy +0.005 psiA
 100 psi / 10 bar / 1MPa Range: Gauge Accuracy +0.002 psiA

Includes all effects of linearity, hysteresis, repeatability, temperature, and stability for one year.

Exposure to environmental extremes of temperature, shock, and/or vibration may warrant a more frequent recertification period.

APMi modules must be exercised and re-zeroed whenever exposed to significant changes in environmental conditions to achieve these specifications. To exercise a module, cycle the module between zero (ambient barometric pressure) and the pressure of interest. A properly exercised module will return to a zero reading (or return to the same ambient barometric reading).

ACCURACY CONTINUED

All models indicate vacuum, but vacuum specification applies only where specified.

Not recommended for continuous use at high vacuum. Refer to [XP2i-DP data sheet](#) for gauges that are intended for continuous high vacuum use.

The BARO option for the HPC50 Series allows you to toggle between gauge and absolute pressure using the same APMi module.

SENSOR

Wetted Materials:(wrench tight) 316 stainless steel
 (finger tight) 316 stainless steel
 and Viton® with internal o-ring
 (15 psi / 1 bar / 100 kPa) 316 stainless steel and Viton®

Diaphragm Seal FluidSilicone Oil

Connection:Crystal CPF Female

All welded, with a permanently filled diaphragm seal.

Metal to metal cone seal; O-ring can be removed if necessary.

1/4" male NPT adapter is included unless BSP or M20 is specified.

1/4" medium pressure tube system is compatible with HIP LM4 and LF4 Series, Autoclave Engr SF250CX Male and Female Series.

OUTPUT

Pressure Resolutionup to 6 digits

Display Updateup to 10 per second

Pressure resolution and display update are the maximum values available. The resolution of your Crystal device may be different.

PRESSURE OVERLOAD

Overload Alarm:“+OL” in display at 110% F.S.

OPERATING TEMPERATURE

Temperature Range:-20 to 50° C (-4 to 122° F)

< 95% RH, non-condensing. No change in accuracy over operating temperature range, except as noted in the accuracy specifications. APMi must be zeroed to achieve rated specification.

Applies to all modules.


STORAGE TEMPERATURE

Temperature Range:-40 to 75° C (-40 to 167° F)

ENCLOSURE

Dimensions:2.9 x 1.1 in (74.0 x 27.0 mm)

Weight0.39 lbs (176.0 g)



ATMi Modules

TEMPERATURE MEASUREMENT

Accuracy:..... $\pm(0.015\%$ of rdg) + 0.02 Ohm
 Range:0 to 400 Ohms
 Resolution:0.01 on all scales
 Units:°C, K, °F, R, Ω
 TCR:0.003850 $\Omega/\Omega/^{\circ}\text{C}$ (IEC 60751)
 Wiring:4-wire support
 Includes all effects of linearity, hysteresis, repeatability, temperature, and stability for one year.
 Combine with part number 127387 for a -45 to 150° C temperature sensor. Contact us to add a calibration certificate.

OUTPUT

Temperature Resolution0.01
 Display Updateup to 10 per second
 Temperature resolution and display update are the maximum values available. The resolution of your Crystal device may be different.

COMMUNICATION

Connector.....6-pin LEMO
 Serial.....RS-422, 9600 baud, 8 data, no parity, 1 stop
 Protocol.....ASCII command language

OPERATING TEMPERATURE


Temperature Range.....-20 to 50° C (-4 to 122° F)
 < 95% RH, non-condensing. No change in accuracy over operating temperature range. Gauge must be zeroed to achieve rated specification.
 Applies to all modules.

STORAGE TEMPERATURE

Temperature Range.....-40 to 75° C (-40 to 167° F)

ENCLOSURE

Dimensions.....2.5 x 1.1 in (63.3 x 27.0 mm)
 Weight0.31 lbs (141.0 g)



The proper selection of the RTD sensing element is very important as the error associated with this device is the majority of the overall system measurement uncertainty. IEC 751 is the standard that defines the temperature versus resistance for 100 Ω , 0.00385 $\Omega/\Omega/^{\circ}\text{C}$ platinum RTDs. IEC 751 defines two classes of RTDs: Class A and B. Class A RTDs operate over the -200 to 630° C range versus -200 to 800° C for the Class B elements. For example, the Class A uncertainty is about half that of the Class B elements as illustrated in the following table.

Temperature °C	Class A						Class B			
	HPC50/ATMi Uncertainty		Class A Uncertainty		HPC50/ATMi + Class A Uncertainty		Class B Uncertainty		HPC50/ATMi + Class B Uncertainty	
	$\pm\Omega$	$\pm^{\circ}\text{C}$	$\pm\Omega$	$\pm^{\circ}\text{C}$	$\pm\Omega$	$\pm^{\circ}\text{C}$	$\pm\Omega$	$\pm^{\circ}\text{C}$	$\pm\Omega$	$\pm^{\circ}\text{C}$
-200	0.02	0.05	0.24	0.55	0.24	0.55	0.56	1.30	0.56	1.30
-40	0.03	0.08	0.09	0.23	0.10	0.24	0.20	0.50	0.20	0.51
0	0.04	0.09	0.06	0.15	0.07	0.17	0.12	0.30	0.12	0.31
50	0.04	0.10	0.10	0.25	0.10	0.27	0.21	0.55	0.22	0.56
100	0.04	0.11	0.13	0.35	0.14	0.37	0.30	0.80	0.31	0.81
150	0.04	0.12	0.17	0.45	0.17	0.46	0.39	1.05	0.39	1.06
200	0.05	0.13	0.20	0.55	0.21	0.56	0.48	1.30	0.48	1.31
400	0.06	0.17	0.33	0.95	0.33	0.96	0.79	2.30	0.79	2.31
600	0.07	0.21	0.43	1.35	0.44	1.37	1.06	3.30	1.06	3.31
800	0.08	0.25	0.52	1.75	0.53	1.77	1.28	4.30	1.28	4.31

Specifications

Gauge Pressure Accuracy (P1, P2, and APMi)

Includes all effects of linearity, hysteresis, repeatability, temperature, and stability with the operating temperature range for one year.

Note: Exposure to environmental extremes of temperature, shock, or vibration may warrant a more frequent calibration period.

The HPC50 Series must be exercised and re-zeroed whenever exposed to significant changes in environmental conditions to achieve these specifications. To exercise a gauge, cycle the gauge between zero (ambient barometric pressure) and the pressure of interest. A properly exercised gauge will return to a zero reading (or return to the same ambient barometric reading).

► Gauge Pressure (psi)

• 18 to 28° C

0 to 30% of Range	±(0.01% of Full Scale)
30 to 110% of Range.....	±(0.035% of Reading)
Vacuum*	±(0.05% of Full Scale**)

• -20 to 50° C

0 to 30% of Range	±(0.015% of Full Scale)
30 to 110% of Range.....	±(0.050% of Reading)
Vacuum*	±(0.05% of Full Scale**)

*Applies to 300 psi and lower ranges only.

Vacuum Range = -14.5 psi.

**Full Scale is the numerical value of the positive pressure range.

! **CAUTION:** Not recommended for continuous use below -14.5 psig. Refer to the [XP2i-DP](#) data sheet for gauges that are intended for continuous high vacuum use.

► Absolute Pressure with BARO Option (psiA)

All absolute accuracies are equivalent to the gauge pressure accuracies, except as noted below.

15 psi Range	Gauge Accuracy +0.005 psiA
30 psi Range	Gauge Accuracy +0.005 psiA
100 psi Range	Gauge Accuracy +0.002 psiA

► **Differential Pressure**

The Tare function can improve differential pressure measurement uncertainties. Requires the use of an equalizing valve. Use the higher range sensor specification when two different ranges are selected.

Full Scale Range of Both Sensors (psi)	The Greater of (+/-)				% of DP Reading
	psi	mbar	inH ₂ O	mmH ₂ O	
15	0.00015	0.01	0.004	0.1	0.035%
30	0.0005	0.04	0.014	0.4	
100	0.0015	0.10	0.04	1.0	
300	0.005	0.4	0.14	4.0	
1000	0.02	1.0	0.4	10.0	
3000	0.05	4.0	1.4	n/a	
10000	0.2	10.0	4.0	n/a	

or

Unit is enabled in CrystalControl

• **Without tare function:**

±(0.05% of static line pressure reading)

Barometric Reference (BARO)

Accuracy ± 0.00725 psi, ± 0.5 mbar

Range 10.153 to 15.954 psiA, 700.0 to 1100.0 mbarA

Units and Resolution.....psi: 0.001
inHg: 0.001
mmHg: 0.01
mbar 0.1

Accuracy specifications include all effects of linearity, hysteresis, repeatability, temperature, and stability within the specified operating temperature range for one year.

Note: Exposure to environmental extremes of temperature, shock, and/or vibration may warrant a more frequent recertification period.

Pressure Sensor (P1, P2, and APMi)

Wetted Materials.....(Wrench Tight) 316 stainless steel

(Finger Tight) 316 stainless steel and Viton® (internal o-ring)

(15 psi / 1 bar / 100 kpa) 316 stainless steel and Viton® (internal o-ring)

Diaphragm Seal Fluid:Silicone Oil

Connection:Crystal CPF Female

Pressure Conversions

1 PSI =	27.6806 inches of water column (water at 4°C [39.2°F])
	703.087 millimeters of water column (water at 4°C [39.2°F])
	70.3087 centimeters of water column (water at 4°C [39.2°F])
	2.03602 inches of mercury (mercury at 0°C [32°F])
	51.7149 millimeters of mercury (mercury at 0°C [32°F])
	6.8948 kilopascals
	0.070307 kilograms per square centimeter
	0.068948 bar
	68.948 millibar
	0.0068948 megapascals

Electrical

All accuracy specifications include all effects of linearity, hysteresis, repeatability, temperature, and stability within the specified operating temperature range for one year.

Note: Exposure to environmental extremes of temperature, shock, and/or vibration may warrant a more frequent recertification period.

Connection.....	4 mm jacks
Maximum Voltage	45 VDC

► Current (mA) Input

Accuracy	±(0.015% of rdg + 0.002 mA)
mA Range	0 to 55 mA
Percent Range	0-20, 4-20, 10-50
Max Allowable Current.....	93.3 mA
Resolution.....	0.001 mA or 0.01%
Units	mA, scaling, % error, % flow
Input Resistance.....	< 4.99 Ω
Voltage Burden @ 20mA	< 0.10 V
Voltage Burden @ 50mA	< 0.250 V
HART Resistor	250 Ω

- **Current (mA) Sink**
Accuracy± (0.015 of rdg + 0.002 mA)
Range0 to 25 mA
Step Time1 to 999 seconds
Ramp Time5 to 999 seconds

- Voltage (VDC) Input**
Accuracy±(0.015 % of rdg + 2 mV)
Range0 to 28 VDC
Maximum Allowable Voltage.....30 VDC
Resolution.....0.001 VDC

- **Switch Test**
Switch TypeDry Contact
Closed State Resistance.....< 1K Ω
Open State Resistance> 100K Ω
Sample Rate:10 Hz

-
- Display**
Screen.....320 x 240 pixel graphical display
Display Rate3 readings/second (standard)
-

- Operating and Storage Temperature**
Operating Temperature Range ...-20 to 50° C (-4 to 122° F)
Storage Temperature Range.....-40 to 75° C (-40 to 167° F)

Power

The HPC50 can be powered by batteries or USB.

! WARNING: Do not use the USB port in a hazardous area.

► Power Icon States

The HPC50 battery icon indicates how much battery life is remaining.



► Battery Power

The HPC50 uses three(3) size AA (LR6) alkaline batteries.

Note: If the batteries discharge too deeply, the calibrator will automatically shut down to avoid battery leakage and false measurements.

► Approved Batteries

Approved Battery Type	CSA		ATEX & IECEx	
	Temperature Class	Ambient Temperature	Temperature Class	Ambient Temperature
Rayovac Max Plus 815	T3	-20 to 50° C	T4	-20 to 50° C
Energizer E91 *	T4	-20 to 40° C		
Duracell MN1500	T3	-20 to 40° C	T3	-20 to 50° C
Energizer EN91 *				

Replace batteries with approved type in non-hazardous locations only.

* Energizer is manufactured by Energizer Holdings, Inc., and the Eveready Battery Company, Inc.

► Battery Life

Depending on how the HPC50 is configured, the battery life may differ. All numbers in the table below are without the use of the backlight, which will decrease the battery life.

Configuration	Battery Life, In Hours
HPC50 with no external modules	35
HPC50 with one external module	25
HPC50 with two external modules	12

► Battery Replacement

The HPC50 uses three AA batteries. Unscrew the four flathead screws to gain access to the battery compartment. Replace the batteries taking care to note polarity for their proper installation. Failure to properly seal the battery compartment may allow water damage that could permanently compromise the HPC50.

RANGES AND RESOLUTIONS

psi	bar	kPa/MPa	Overpressure	psi	kg/cm2	inHg	inH2O	mmHg	mmH2O	kPa	bar	mbar	MPa
15PSI	1BAR		3.0 x	0.0001	0.00001	0.001	0.01	0.01	0.1	0.001	0.00001	0.01	
			3.0 x	0.0001	0.00001	0.001	0.01	0.01	0.1	0.001	0.00001	0.01	
		100KPA	3.0 x							0.001	0.00001	0.01	
30PSI	3BAR		3.0 x	0.001	0.0001	0.001	0.01	0.01	1	0.01	0.0001	0.1	0.00001
			3.0 x	0.001	0.0001	0.001	0.01	0.01	1	0.01	0.0001	0.1	0.00001
		300KPA	3.0 x							0.01	0.0001	0.1	0.00001
100PSI	10BAR		2.0 x	0.001	0.0001	0.01	0.1	0.1	1	0.01	0.0001	0.1	0.00001
			2.0 x	0.001	0.0001	0.01	0.1	0.1	1	0.01	0.0001	0.1	0.00001
		1MPa	2.0 x							0.01	0.0001	0.1	0.00001
300PSI	30BAR		2.0 x	0.01	0.001	0.01	0.1	0.1		0.1	0.001	1	0.0001
			2.0 x	0.01	0.001	0.01	0.1	0.1		0.1	0.001	1	0.0001
		3MPa	2.0 x							0.1	0.001	1	0.0001
1KPSI	100BAR		2.0 x	0.01	0.001	0.1				0.1	0.001		0.0001
			2.0 x	0.1	0.001	0.1				0.1	0.001		0.0001
		10MPa	2.0 x							0.1	0.001		0.0001
3KPSI	300BAR		1.5 x	0.1	0.01	0.1				1	0.01		0.001
			1.5 x	0.1	0.01	0.1				1	0.01		0.001
		30MPa	1.5 x							1	0.01		0.001
10KPSI	700BAR		1.5 x	0.1	0.01					1	0.01		0.001
			1.5 x	0.1	0.01					1	0.01		0.001
		70MPa	1.5 x							1	0.01		0.001

Resolutions shown are the maximum resolutions available. The resolution of your Crystal device may be different.

* CPF adaptor fitting is not included. 1/4" medium pressure tube system is compatible with HIP LM4 and LF4 Series, Autodave Engr SF250CX Male and Female Series. [See our CPF data sheet](#) for additional adaptor fittings.

Ordering Information

Number of Sensors	1st Pressure Range P/N	2nd Pressure Range P/N	BARO Option	Adapter
HPC51 (Single)			No (omit)	1/4 NPT (omit)
HPC52 (Dual)			Yes... -BARO	G 1/4 B. -BSP
				M20x1.5 -M20

SAMPLE PART NUMBERS

HPC51-1KPSI Single Sensor (1000 psi) HPC50 with a 1/4" male NPT pressure fitting.

HPC52-3BAR-700BAR-BSP-BARO Dual Sensor (3 bar/700 bar) HPC50 with a 1/4" male BSP pressure fitting and BARO option.

Safety & Certifications

HAZARDOUS LOCATIONS

Every HPC50 Series calibrator includes the following Intrinsic Safety approvals:

	Ex ia IIC T4/T3 Ga FTZU 18 ATEX 0043X		Exia Intrinsically Safe and Non-Incendive for Hazardous Locations: Class I, Division 1, Groups A, B, C, and D; Temperature Code T4/T3. Class I, Zone 0, AEx ia IIC T4/T3 Ga.
	Ex ia IIC T4/T3 Ga IECEx FTZU 18.0012X		Sécurité intrinsèque et non incendiaire pour dangereux Lieux: Classe I, Division 1, Groupes A, B, C, and D; Code de température T4/T3. Classe I, Zone 0, AEx ia IIC T4/T3 Ga.

Entity Parameters

mA/V port	APMi/ATMi ports
Ui = 28 V	Uo = 4.95 V
Ii = 94 mA	Io = 731 mA
Pi = 654 mW	Po = 880 mW
Ci = 3 nF	Co = 83.5 µF
Li = 0	Li = 32.2 µH
	Co = 9.2 µF
	Lo = 12 µH

! WARNINGS: The following warnings apply to the HPC50 Series:

- Do not use the USB connector in hazardous locations.
- Replace batteries in non-hazardous locations and with approved types only.
- Do not mix battery types or manufacturers.
- T4 or T3 Temperature Class is based on selection of approved battery. See [Approved Batteries](#).
- **Special conditions for safe use:**
The equipment shall not be installed in a location where external conditions are conducive to the buildup of electrostatic charge.

CERTIFICATIONS

The HPC50 Series has been tested and certified to comply with a variety of international standards.

	This HPC50 complies with the Australian Radiocommunications (Electromagnetic Compatibility) Standard 2008.		This HPC50 is approved for use as a portable test instrument for Marine use and complies with DNV GL Rules for Classification of Ships, High Speed & Light Craft, and Offshore Units.
	Crystal Engineering declares that the HPC50 is in accordance with the ATEX Directive, the Electromagnetic Compatibility Directive, and the Pressure Equipment Directive per our declaration(s).		

HPC50 Series Operation Manual

MULTI-LANGUAGE SAFETY INSTRUCTIONS

English (English)

If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.

► Safety Instructions for Hazardous Locations

- Do not use the USB connector in a hazardous location.
- Replace batteries in non-hazardous locations, with approved batteries, only. Do not mix battery types or manufacturers.
- It is the users responsibility to understand the proper application of this product in potentially explosive atmospheres.

Approved Battery Type	CSA		ATEX & IECEx	
	Temperature Class	Ambient Temperature	Temperature Class	Ambient Temperature
Rayovac Max Plus 815	T3	-20 to 50° C	T4	-20 to 50° C
Energizer E91	T4	-20 to 40° C		
Duracell MN1500				
Energizer EN91	T3	-20 to 40° C	T3	-20 to 50° C

Replace batteries with approved type in non-hazardous locations only.

► Special Conditions for Safe Use

The equipment must not be installed in a location where external conditions are conducive to electrostatic charge build-up.

Français (French)

Si l'équipement est utilisé d'une manière non spécifiée par le fabricant, la protection fournie par l'équipement peut être altérée.

► Instructions de sécurité pour les Zones Dangereuses

- Ne pas utiliser le connecteur USB dans une Zone Dangereuse.
- Remplacez les piles dans des Zones non-dangereuses, avec les piles appropriées, uniquement. Ne mélangez pas les types de piles ni les fabricants.
- Il est de la responsabilité de l'utilisateur de bien comprendre l'application appropriée de ce produit en atmosphères explosives.

Type de Pile Approuvée	CSA		ATEX & IECEx	
	Classement Température	Température Ambiante	Classement Température	Température Ambiante
Rayovac Max Plus 815	T3	-20 to 50° C	T4	-20 to 50° C
Energizer E91	T4	-20 to 40° C		
Duracell MN1500				
Energizer EN91	T3	-20 to 40° C	T3	-20 to 50° C

La classe de température T4 ou T3 est basée sur la sélection de la pile approuvée.

► Conditions spéciales pour une utilisation en toute sécurité

L'équipement ne doit pas être installé dans un endroit où les conditions extérieures sont propices à l'accumulation de charge électrostatique.

TROUBLESHOOTING

The HPC50 Series is a very high performance calibrator. Due to the high resolution of this product, you may observe conditions that appear to be defects in the product, but are in fact a result of being able to read and measure pressure to a degree not possible with other instruments.

Noisy or unstable reading when used with fluids

When calibrating or comparing the indicated pressure from an HPC50 against a hydraulic deadweight tester or piston gauge, the reading on the HPC50 may appear unstable—the least significant digit jumps up and down several counts.

► **Reason**

Gas (usually air) is trapped in the line between the HPC50 and the deadweight tester. What is actually happening is the mass is oscillating up and down, and the combination of gas and fluid is acting like a spring. At higher pressures (above 2000 psi, typically) this may eventually diminish, as the gas dissolves into the fluid.

► **Solution**

Evacuate all tubing with a vacuum pump before introducing fluid into the system.

Non-repeatability of pressure measurements

When checking the calibrator against a hydraulic deadweight, increasing pressure measurements do not match decreasing pressure measurements.

► **Reason**

As in the previous note, gas has dissolved into the hydraulic fluid. When decreasing the pressure, the dissolved gas then leaves the fluid, but at an uneven rate, so a small pressure differential (due to fluid head pressure) may exist between the reference deadweight and the gauge being tested.

► **Solution**

Evacuate all tubing with a vacuum pump before introducing fluid into the system.

Slow return to zero and/or non-repeatability of pressure measurements

► **Reason**

Pressure port is obstructed.

► **Solution**

Clean with low pressure fluid. Do not touch diaphragm as damage will result.

CALIBRATION

If adjustment is required, we recommend returning the HPC50 to the factory. Factory service offers benefits you won't find anywhere else. Factory calibration tests your HPC50 at a variety of temperatures utilizing NIST traceable standards, resulting in calibration certificates that provide performance data over temperature. Our calibration facilities are A2LA accredited (cert #2601.01) to ISO 17025:2005 & ANSI/NCSL Z540-1-1994. A2LA is internationally recognized as an accreditation body by the International Laboratory Accreditation Cooperation, ILAC. Furthermore, upgrades may be available to add or enhance operating features. We designed the product to last, and we support it so that you can get the most from your investment.

Under normal operating conditions, we recommend the HPC50 be calibrated on an annual basis. Your quality system may require more or less frequent calibration, or your experience with the gauge, or operating environment may suggest longer or shorter intervals.

Although we prefer that you return the HPC50 to us for calibration, ordinary recertification and/or adjustments may be performed by any qualified personnel with appropriate training and equipment. The following instructions are ONLY intended for such qualified personnel with appropriate test equipment. We recommend that the calibration standards used have a minimum rated accuracy of 0.008% of reading, or equivalent in terms of percent of full scale. This level of accuracy requires the use of piston (deadweight) gauges or very high performance pressure controllers.

CRYSTALCONTROL There are no internal potentiometers. Each of the HPC50's sensors has a "span factor" (userspan), set to approximately 1 (as shipped from the factory). As components age this may need to be changed to a value slightly higher or lower, to slightly increase or decrease all readings. This adjustment can be made with a computer through CrystalControl.

Calibration of P1 and P2

CRYSTALCONTROL "Zero" the HPC50, then record displayed pressure for two or more pressure points. Determine if the HPC50 would benefit from an overall increase or decrease of the indicated pressures. Adjust userspan accordingly and validate results.

Calibration for Barometric Reference Module (BARO)

CRYSTALCONTROL The BARO module can be calibrated by selecting the Edit Calibration Data button while within the BARO Config screen. Enter Userspan and Offset information directly, or you can use the Calibration Wizard to calculate the optimum values for a 1 or 2 point calibration.

- 1 Remove the mounting bracket on the back of the HPC50, exposing the barometric sensor port.
- 2 Connect a flexible 4.8 mm [3/16"] ID tubing from your clean pneumatic calibration reference to the BARO sensor.
You can also order the BARO calibration kit (P/N 4547), which includes the tubing.

CAUTION: Do not subject the BARO sensor to pressures less than 700 mbarA (10.153 PSIA), or greater than 1100 mbarA (15.954 PSIA), as this may cause permanent damage. Use only clean a clean dry pneumatic source.

CAUTION: Direct contact with the surface of the BARO sensor may cause permanent damage. Direct sunlight on exposed BARO sensor may affect readings slightly.

ACCESSORIES AND REPLACEMENT PARTS

P/N 104203 Test Lead Kit

Lead Kit, Red and black test leads with clips. (Included as standard)

P/N 6215 Protective Boot

Static dissipative protective boot. (Included as standard)

P/N 3951 Mini-USB Cable

The durable and high-speed Micro-USB cable enables data transfer in the most convenient form. (Included as standard)

P/N 3009 Hard Carrying Case

Aluminum carrying case with molded eggshell foam interior.

P/N 2888 Waterproof Carrying Case

Hard plastic carrying case with molded eggshell foam interior.

MPM-1/4MPT CPF Male to 1/4" Male NPT Fitting

(Included as standard)

MPM-1/4BSPM CPF Male to 1/4" Male BSP Fitting

(Included with -BSP)

MPM-M20x1.5M CPF Male to M20 Male Adapter

(Included with -M20)

CONTACT US

WARRANTY

Crystal Engineering Corporation warrants the HPC50 Series Calibrator to be free from defects in material and workmanship under normal use and service for one (1) year from date of purchase to the original purchaser. It does not apply to batteries or when the product has been misused, altered or damaged by accident or abnormal conditions of operation.

Crystal Engineering will, at our option, repair or replace the defective device free of charge and the device will be returned, transportation prepaid. However, if we determine the failure was caused by misuse, alteration, accident or abnormal condition of operation, you will be billed for the repair.

CRYSTAL ENGINEERING CORPORATION MAKES NO WARRANTY OTHER THAN THE LIMITED WARRANTY STATED ABOVE. ALL WARRANTIES, INCLUDING IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE, ARE LIMITED TO A PERIOD OF ONE (1) YEAR FROM THE DATE OF PURCHASE. CRYSTAL ENGINEERING SHALL NOT BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, WHETHER IN CONTRACT, TORT OR OTHERWISE.

Note: (USA only) Some states do not allow limitations of implied warranties or the exclusion of incidental or consequential damages, so the above limitations or exclusions may not apply to you. This warranty gives you specific legal rights and you may have other rights which vary from state to state.

