
## Configuring your display

- 1 Visit www.lascarelectronics.com/software/panelpilot-m to download PanelPilot M software onto your PC.
- 2 Connect the device to your PC using a standard mini USB cable CABLE USB A-MF (not supplied).
- 3 Open up the software on your PC and follow step-by-step instructions for configuring your display.



#### **Dual-In-Line IDC (DIL Connector)**

The DIL IDC socket provides an alternative connection method to the screw-terminals. It also includes provision for future expansion using data buses and alarm outputs.









# **Quickstart Guide**

Issue 2 07/2018

## Getting to know your display

All PanelPilot compatible displays share the following features:





## Mounting

Your display can be mounted in a panel up to 3mm deep. We recommend using the silicone seal provided for panels of 2mm or less. Please consult the Mounting section of the appropriate data sheet for exact cut-outs and mounting methods for your display.

#### **Screw Terminal Connection**

There are four screw terminals for connecting single and dual input applications. They are labelled 1 to 4 as follows:

1 IN2 2 IN1 3 OV 4 V+



**N.B.** For safety reasons, the meter should be isolated from both the supply and signal voltages before connecting the USB.

#### **Default Configuration**

Each display is supplied pre-configured as a 0 to 10V d.c. single-ended combined analogue and digital voltmeter. Connection should be made via the screw terminals as follows:

1	IN2	No connection
2	IN1	Connect to 0 to 10V d.c. signal voltage
3	0V	Connect to 0V
4	V+	Connect to 4 to 30V d.c. supply voltage

Please consult the Applications section of the appropriate data sheet for further details of wiring schemes, cautions, etc.

#### What's in the box?

- Panel meter
- Fixing kit
- Quick start guide

#### Accessories

- CABLE USB A-MF (standard mini USB cable)

Issue 2 07/2018