

EXTECH *Product* DATASHEET

INSTRUMENTS

Hygro-Thermometer Humidity Alert w/Dew Point

Programmable Alarms warn of High or Low Humidity Conditions

Features:

- Large, easy-to-read triple LCD displays % Relative Humidity, Temperature and Dew Point
- %RH audible and visual alarms, with adjustable set points, alert when humidity exceeds set limit
- Max/Min with Reset function
- Complete with built-in stand, wall mount bracket, and 2 AAA batteries



Specifications	
Humidity:	10 to 99%
Temperature:	14 to 140°F (-10 to 60°C)
Basic Accuracy:	±4%RH; ±1.8°F/1°C
Dimensions:	4.3x3.9x0.78" (109x99x20mm)
Weight:	6oz (169g)



Monitoring Dew Point levels in a Basement for potential mold growth.



Indicates Humidity and Temperature levels in Production areas.



Alerts low Humidity levels in Computer rooms to help prevent electrostatic conditions.



Checks the Humidity and Temperature levels for optimal plant growth in greenhouses.

Applications

- In summertime, identifies and warns when conditions for mold growth exist
- In wintertime, identifies and warns when low humidity conditions for static electricity exist
- Air temperature and dew point temperature indicate where condensation may occur
- Monitor conditions in laboratories, storage areas and other controlled environment settings

Ordering Information:

445814Humidity Alert Hygro-Thermometer with Dew Point

EXTECH INSTRUMENTS CORPORATION
 285 Bear Hill Road, Waltham, MA 02451-1064, U.S.A.
 Phone: 781-890-7440 • FAX 781-890-7864

ISO 9001:2000 CERTIFIED

"Make mine an Extech!"™
www.extech.com



01/12/06 - R2