




No. 99MAG023M3 / テストインジケータ

















Dial Test Indicator

To ensure operator safety, use this instrument in conformance with the directions and specifications and specifications and specifications in this User's Manual. Non-conformance to the instructions may compromise safety.

Be sure to perform reference point adjustment by following points to notice below.

- Do not perform the adjustment at sites where the temperature will change abruptly. Thermally stabilize the instrument

- sufficiently at room temperature.

 Wipe oil and dust off the both contact point and master gage using a gauze or chamois skin
- Perform reference point setting and measurement in the same posture of the product
- Use a master gage like a setting standard which is periodically calibrated.

 After use, take corrosion prevention measures. Corrosion can cause the caliper to malfunction.

