

Measuring procedure	Sensor model	Type	Measuring range	Uncertainty (of reading)	Minimum measuring spot	Available in combination with		
						MiniTest 725	MiniTest 735	MiniTest 745
Magnetic-induction sensors	F 0.5M-0 F 0.5M-45° F 0.5M-90°	A	0 ... 0.5 mm	$\pm (0.5 \mu\text{m} + 0.75 \%)$	Ø 3 mm		X	X
	F 1.5	B / E	0 ... 1.5 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm	X	X	X
	F 1.5-90°	C	0 ... 1.5 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm		X	X
	F2	B / E	0 ... 2.0 mm	$\pm (1.5 \mu\text{m} + 0.75 \%)$	Ø 10 mm	X	X	X
	F2.6	B / E	0 ... 2.6 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm	X	X	X
	F 5	B / E	0 ... 5.0 mm	$\pm (1.5 \mu\text{m} + 0.75 \%)$	Ø 10 mm	X	X	X
	F 15	D	0 ... 15 mm	$\pm (5.0 \mu\text{m} + 0.75 \%)$	Ø 25 mm	X	X	X
Eddy current sensors	N 0.7	B / E	0 ... 0.7 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm	X	X	X
	N 0.7-90°	C	0 ... 0.7 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm		X	X
	N 2.5	B / E	0 ... 2.5 mm	$\pm (1.5 \mu\text{m} + 0.75 \%)$	Ø 10 mm	X	X	X
	N 7	D	0 ... 7.0 mm	$\pm (5.0 \mu\text{m} + 0.75 \%)$	Ø 20 mm	X	X	X
Dual sensors	FN 1.5	B / E	F: 0 ... 1.5 mm N: 0 ... 0.7 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm	X	X	X
	FN 1.5-90°	C	F: 0 ... 1.5 mm N: 0 ... 0.7 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm		X	X
	FN 2.6	B / E	F: 0 ... 2.6 mm N: 0 ... 1.0 mm	$\pm (1.0 \mu\text{m} + 0.75 \%)$	Ø 5 mm	X	X	X
	FN 5	B / E	F: 0 ... 5.0 mm N: 0 ... 2.5 mm	$\pm (1.5 \mu\text{m} + 0.75 \%)$	Ø 10 mm	X	X	X

Type A:
Miniature sensors F 05 M



Type B:
Sensors F 1.5, F 2, F 2.6, F 5,
N 07, N 2.5,
FN 1.5, FN 2.6, FN 5



Type C:



Sensors F 1.5-90°, N 0.7-90°, FN 1.5-90°

Type D:
Sensors F 15, N 7



Type E:
Heavy-duty sensor

