

# TCDCS DROP CABLE STRIPPER INSTRUCTIONS



**Step 1.** Pull plunger to open tool body.



**Step 2.** Insert the fiber optic cable.



**Step 3.** Close the tool making sure the plunger is in the locked position.



**Step 4.** Pull the cables and tool in the opposite directions to strip the cable.



## TCDCS SPECIFICATIONS

**Slits Drop Cable:** 7.9mm to 8.3mm

**Length:** 3.26" (82.8mm)

**Weight:** 0.15lb (68g)

**Material Body:** ABS

**Blade:** SK5

**REPLACEMENT BLADE SETS**  
TCDCS-2