Twist-On Connectors

- · Bright nickel finish solid brass or zinc body
- · Utilizes captive, self-energizing gold-plated center contact
- · Field installable; Completely reusable
- · No solder or crimping tools needed
- · Requires open ended wrench
- · Available in packs of 10



302-1TP

BNC Male 1 Pc Twist-On 50 Ohm




302-4TP

BNC Male 1 Pc Twist-On 50 Ohm

Twist-On Connector Assembly Procedure



1. Trim cable as ahown using Strip Tool P/N GST-1. Trim center conductor end at a 45 ° angle. *Note: Do not fold back braid



2. Push connector onto cable while twisting in a clockwise direction Continue until connector will go no further.



3. Using open ended wrench on hex body, twist connector an additional 3 turns.



GET-301 - UT

Universal Crimp Tool

Ordering Information

Part Number	Description
302-1TP	BNC Male 1 Pc Twist-0n, 50 0hm RG58, RG59 TFE, & RG62 TFE. 10 PK
302-4TP	BNC Male 1 Pc Twist-0n, 50 0hm RG59 PVC, & RG6 TFE. 10 PK
GST-1	Wire Stripper RG6, RG58, RG59, RG62
GET-301-UT	Universal Crimp Tool for Crimp-On BNC for 301-00TP, 301-1TP, 301-4TP



GST-1

Coaxial Wire Stripper Tool











