


PDA2300 Enclosure Series Instruction Manual

1. Place metal plate inside the enclosure as shown in the picture below.
2. Proceed to install mounting brackets supplied with the meter.



LIM2300_B 04/15

PRECISION DIGITAL CORPORATION

